

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL. BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS)
UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = leyso	DESIGNED -	REVISED -	J.A.F. 04-03		SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS		F.A.U.	SECTION	COUNTY	TOTAL SHEET	
W:\diststd\22x34\tc18.dgn		DRAWN -	REVISED -	J.A.F. 02-06	STATE OF ILLINOIS				3778	07-00042-00-CH	соок	20 12
	PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED -	S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION		SHEET NO 1 OF 1 SHEETS			TC-18	CONTRACT	NO. 63489
	PLOT DATE = 1/26/2010	DAIL -	REVISED -	S.P.B. 12-09		SCALE: NONE	STA. TO STA.	FED. ROAD	DIST. NO. 1 ILLINOIS FED. A	ID PROJECT CN	MM-8003(776)	