

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES.

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = qureshipa	DESIGNED -	REVISED - J.A.F. 04-03			SIGNING FOR FLAGGING OPERATIONS		RTE. SECTION	COUNTY TOTAL SHEET NO.
c:\pw_work\pwidot\qureshiya\dØ111256\Dist	td.dgn	DRAWN -	 REVISED - J.A.F. 02-06 REVISED - S.P.B. 01-07	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION		AT WORK ZONE OPENINGS		3887 A-R-N-1 TC-18	KANE 77 65 CONTRACT NO. 62914
	PLOT SCALE = 50.0000 ' / IN. PLOT DATE = 3/10/2010	CHECKED -	 REVISED - S.P.B. 01-07 REVISED - S.P.B. 12-09	DEPARTMENT OF TRANSPORTATION	SCALE: NONE	SHEET NO. 1 OF 1 SHEETS STA.	TO STA.	FED. ROAD DIST, NO. 1 ILLINOIS FED. AL	The same of the sa