

| SHEET REVIEW | | | REVISIONS | | SCALE: N, | /A | | MaClura | |
|--------------|------|---------------------------------------|-----------|------|---------------|----------|------------------------------------|-----------------------------------------------------------|----|
| AGENCY | DATE | NO. | ITEM | DATE | DRAWN BY: M | is | | MICLIUIE | |
| | | | | | | | | Engineering Associates, Inc. | l |
| | | · · · · · · · · · · · · · · · · · · · | | | CHECKED BY: J | MH - | 7282 Argus Drive (815) 398-2332 | Rockford, Illinois 61107-5837 FAX (815) 398-2496 | 71 |
| | | | | | DATE: AUGUST | 13, 2010 | Design Firm Licens | se: Illinois 184-000816 e Engineering Associates, Inc. | FI |

H:\08-008 I:I, Monty

| 06-00543-00-BT WINNEBAGO 148 148 | F.A | . RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. |
|-----------------------------------------------|---------------------|--------|----------------|-----------|--------------|-----------|
| FED ROAD DIST NO ULLINOIS CONTRACT NO 2552 | | | 06-00543-00-BT | WINNEBAGO | 148 | 148 |
| TEB. ROAD DIST. NO. TEENNIS CONTRACT NO. 8552 | FED. ROAD DIST. NO. | | | ILLINOIS | CONTRACT NO. | 85521 |

Post (Options: 2" x 4" Or 24" Min. Dia. Wood; Steel 1.33 Lbs/Ft. Min.)

> 18 Oz. Nylon Reinforced PVC Fabric (300 psi Test)

GENERAL NOTES

I. Floating turbidity barriers are to be paid for under the contract unit price for Floating Turbidity Barrier, LF.

2. Staked turbidity barriers are to be paid for under the contract unit price for Staked Turbidity Barrier, LF.

TURBIDITY BARRRIER RIVERWALK MUSEUM CAMPUS

ROCKEORD II JOB: 04-28-10-008 SHEET NO. 148

0E

148

ILE: H:\08-008 RIVERWALK MUSEUM\DESIGN\DRAWINGS\08-008 TURBIDITY BARRIER DETAIL.DWG

NORTH MAIN STREET