
SECTION THRU DRILLED SOLDIER PILE WALL




DETAIL OF SHEAR STUD PLACEMENT

Untreated timber -Finished grade at Finished grade at lagging Untreated front face front face timber lagging Soldier pile — Geocomposite wall drain - Concrete Concrete facing facing Place 3₄" gap -Place 3₄" gap to allow for to allow for drainage, typ. drainage, typ. *Drainage *Drainage aggregate aggregate *Geotechnical filter *Geotechnical filter *4" Perforated fabric for french -*4" Perforated fabric for french drains drain pipe drain pipe BETWEEN SOLDIER PILES AT SOLDIER PILES


PIPE UNDERDRAIN DETAIL

*Included in the cost of "Pipe Underdrains for Structures, 4""

For pipe underdrain outlets, see Civil Plans.



CONSTRUCTION JOINT DETAIL



EXPANSION JOINT DETAIL

DETAILS SN 022-W046



USER NAME = SAW	DESIGNED	-	LAS	REVISED	-
	CHECKED	-	DAZ	REVISED	-
PLOT SCALE = 5.00 '/ IN.	DRAWN	-	SAW	REVISED	-
PLOT DATE = 5/4/2012	CHECKED	-	LAS	REVISED	-