
## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



NORTH ABUTMENT (Looking North)

## BILL OF MATERIAL

<u> </u>	Unit	Total
Structural Repair of Concrete (Depth Greater Than 5 in.)	Sq. Ft.	21

Repair of the existing abutments shall include but may not be limited to the areas shown. The actual areas to be repaired will be determined by the Engineer at the time of construction.

## <u>LEGEND</u>



Structural Repair of Concrete (Depth greater than 5")

sf. Square Feet

## <u>ABUTMENT REPAIR</u> STRUCTURE NO. 016-1119

	LIN ENGINEERING,LTD.		SHEET NO. 9	F.A.I. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEET NO.
Consulting Engineers Chatham, Illinois				290	(531-3.1,0305-302K)RS-5		-5	COOK	314	204
		12 SHEETS					CONTRACT	NO. 6	S0I38	
Designed By: RH	Checked By: MTH	Drawn By: RH		CED BO	AD DIST NO	ILLINOIS FE	D A1	D DDO IECT		
Date: 12/2009 File: 016-1119 don			I FED. RU	AD DIST. NO	ITELINOTO LE	U. AI	D FRUJELI			