DEPARTMENT OF TRANSPORTATION - € IL Rte. 53 —Existing P.J.S. at Expansion Joint to be removed and replaced with Silicone Joint Sealer, typ. Each Abutment. See detail on Sheet 4 of 4. ` *€ Brg., North Abutment* r © Brg., South Abutment 5 sf -5 sf / PLAN Contractor shall verify that the type of concrete selected shall achieve required strength within the time allotted for construction. See Special Provisions, Deck Slab Repair (Special).

STATE OF ILLINOIS

BILL OF MATERIAL

Repair of the existing deck shall include but may not be limited to the areas shown. The actual areas to be repaired will be determined by the Engineer at the time of construction.

Item	Unit	Total	
Deck Slab Repair (Partial)	Sq. Yd.	3.9	
Deck Slab Repair (Full Depth, Type II)	Sq. Yd.	4.9	
Cleaning and Painting Exposed Rebar	Sq. Ft.	92	
Rebar			

LEGEND

Deck Slab Repair (Full Depth, Type II)



Deck Slab Repair (Partial)



Cleaning and Painting Exposed Rebar on Deck Slab underside

sf Square Feet

DECK SLAB REPAIR STRUCTURE NO. 016-0377

LIN ENGINEERING,LTD.
Consulting Engineers
Chatham, Illinois

SHE	ET	NO. 2		
4 SHEETS				

	F.A.I. SECTION			COUNTY	TOTAL SHEETS	SHEET NO.	
	290 (531-3.1,0305-302K)RS-5				COOK	314	243
					CONTRACT	NO. 6	80138
	FED. RO	DAD DIST. NO	ILLINOIS	FED. A	ID PROJECT		