


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION







SECTION THRU EAST ABUT.



PARTIAL CROSS SECTION
(Looking East)

* Existing dowel rods are to be burned off, ground flush, and sealed with epoxy prior to placement of new beams. Cost included in Removal of Existing PPC Deck Beams. After beams have been erected holes shall be drilled into cap and dowel rods placed. Dowel holes shall be filled with non-shrink grout to top of beam and allowed to cure a minimum of 24 hours prior to grouting the shear keys.





 DESIGNED
 ATH

 CHECKED
 GGE

 DRAWN
 Kyle M. Steffen

 CHECKED
 ATH
 GGE

FEBRUARY 11, 2010

EXAMINED & Carl Program

ENGINEER OF STRUCTURAL SERVICES

PASSED RELIGIOUS ENGINEER OF BRIDGES AND STRUCTURES

ENGINEER OF BRIDGES AND STRUCTURES

REPAIR DETAILS

IL ROUTE 1 OVER ROCK CREEK

SN 035-0002

SHEET NO. 4	F.A.P. RTE.	SECTION				COUNTY	TOTAL SHEETS	SHEET NO.
	782	115I-2				HARDIN	8	7
4 SHEETS	TS					CONTRACT	NO.	
	FED. RO	AD DIST.	NO.	ILLINOIS	FED. A	D PROJECT		