& Brg. 34" \$ studs. 1316 "\$ holes In Bott. Flange -Bearing Assembly


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SHEET NO. 2 TOTAL JEFFERSON 48 46

the reinforcement mat.


4 SHEETS

Contract No. 94905




ELEVATION AT ABUT.

TYPE I ELASTOMERIC EXP. BRG.



BEARING ASSEMBLY


Shim plates shall not be placed under Bearing Assembly.



SIDE RETAINER

Equivalent rolled angle with stiffeners will be allowed in lieu of welded plates.

DESIGNED	ATH
CHECKED	VHV
DRAWN	baliva
CHECKED	ATH VHV



BEAM REACTIONS

		Abutments
R₽	(K)	49.1
R4	(K)	34.9
Imp.	(K)	7.8
R (Total)	(K)	91.8

SECTION A-A

Diaphragm removal and reinstallation may be required to facilitate drilling holes. Cost included with Furnishing and Erecting Structural Steel.

New side retainers, shim plates, connection bolts, and anchor bolts are included with Furnishing and Erecting Structural Steel.

Structural Steel.

See Sheet 3 of 4 for Anchor Bolt installation.

Prior to ordering any material, the Contractor shall verify in the field all bearing height and shim thickness dimensions.

Min. jack capacity = 55 Tons.

Cut existing anchor bolts a minimum of 1" below the top of the existing bearing seat. Top of Concrete Concrete removal. Limit depth to 2" max, or to the top of

© existing <u>1"</u> Anchor Bolt

ANCHOR BOLT REMOVAL DETAIL

Typical except as noted. Cost included with Jacking and Cribbing.

Existing Bearing Assembly	Existing P to be removed using the air-arc method and grind smooth all weld material remaining on the bottom flange. (Typ.)

Burn existing anchor bolts flush with existing concrete surface. Grind existing anchor bolt smooth and seal with epoxy. (Beam 2 S. Abut. & Beam 3, N. Abut. only.)

EXISTING BEARING REMOVAL DETAIL

Cost included with Jacking and Cribbing.

RILL OF MATERIAL

DILL OF WAY		
Item	Unit	Total
Elastomeric Bearing Assembly Type I	Each	8
Jacking and Cribbing	LS	1
Furnishing and Erecting Structural Steel	Pound	.310

REPAIR DETAILS TR 206 OVER FAI 64 JEFFERSON COUNTY SN 041-0080