			VER	RIFIED UTILI	TY INFORM	MOITAN	:	·
TEST HOLE #	SiZE &	TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
109	12"	W	14039071.270	2458870.762	416.37	5.80'	410.57	UTILITY QUALITY LEVEL "A"
110	6"	W	14039113.970	2458692.914	415,48'	3.07	412.41	UTILITY QUALITY LEVEL "A"
110A	1.5"	W	14039114.710	2458692.420	415.51	3.20'	412.31	UTILITY QUALITY LEVEL "A"
111	10"	FM	14039608.580	2457878.964	397.60'	1,94'	395.66	UTILITY QUALITY LEVEL "A"
111A	10"	FM	14039608.580	2457878.964	397.60'	3.01	394.59'	UTILITY QUALITY LEVEL "A"
112	16"	FM	14044181.945	2451425.631	403.80'	2.23'	406.03'	UTILITY QUALITY LEVEL "A"
113	24"	FM	14044195,464	2451426.136	SEE NOTE	SEE NOTE	405.56'	see note
114	24"	FM	14044740.055	2451511.310	398.17	3.56'	401.73	UTILITY QUALITY LEVEL "A"
115	16"	FМ	14044737.878	2451513.982	SEE NOTE	SEE NOTE	402.93	see note
116	16"	FM	14045312.801	2451601.700	SEE NOTE	SEE NOTE	403.44	SEE NOTE
117	24"	FM	14045315.870	2451595.033	399.70'	1.72	401.42 <sup>*</sup>	UTILITY QUALITY LEVEL "A"
118	SEE	NOTE	14045561.693	2452496.355	SEE NOTE	SEE NOTE	414.82'	SEE NOTE
119	SEE	NOTE	14045552.786	2452466.195	SEE NOTE	SEE NOTE	414.43'	SEE NOTE
					to the control of the		***	
			-					
				·				
							.,,	

EST PLE #		TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
		*****					-	
								44.14.14.14.14.14.14.14.14.14.14.14.14.1
				***************************************				The second secon
								and the second s
						****		
	COMPANIA I MATERIA METERS	Nunire mar		***************************************				angunary nyganore no anno 1944 de la Maria de M
				***************************************				
								:
						***************************************		
				······································		and street the street of the s	·	
			:					
							-	
						·,		
						***************************************		
						4.H		
	Landett er in tid balenne er ett ette		-	*****				The second of th
			*	4.44.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.				

NOTES

TEST HOLE #111 & #111A - FOUND (2) 10° PIPES ONE STACKED ON TOP OF THE OTHER, REF. POINT WAS PLACED ON CENTER OF BOTH PIPES.

TEST HOLE #113, #115 & #116 - PIPE WAS EXPOSED ABOVE GROUND.

TEST HOLE #118 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE ONLY ABLE TO PROBE TO A DEPTH OF 15.24' AT WHICH POINT WE FELT SOMETHING SOLID BUT COULD NOT VERIFY IF IT WAS THE SEWER.

TEST HOLE #119 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE NOT ABLE TO EXCAVATE PAST 5'. NO UTILITY WAS FOUND.

ABBREVIATIONS

FM = FORCE MAIN W = WATER MAIN ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



SCALE:

REVISIONS				
NAME	DATE			

SUE INVESTIGATION OF UNDERGROUND UTILITIES VERIFIED UTILITY MATRIX

MISSISSIPPI RIVER BRIDGE PROJECT CONTRACT NO: D-98-061-08

S	PROJECT NO: IL09500610
	DATE: 7/15/10
	DRAWN BY: KLC
	CHECKED BY: EG
	SHEET NO:

	111
DESIGNED EG	REVISED
DRAWN KLC	REVISEO
CHECKED JB	REVISED
DATE 9/15/09	REVISED
	DRAWN KLC CHECKED JB

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

		100101			ជប	1.000.00	3
16 F	** * I		F.A. RTE.	SECTION	COUNTY	TOTAL	SHEET NO.
Mississippi River Bridge		Project			St. Clair	190	122
		***************************************	_		PTB N	0. 147-0	38
SHEET NO.	STA.	TO STA.	FFO. R	GAD DIST NO. HILLINGIS LICID	No. 0-98-061-0	В	