62586, 62589, 62693, 62694, 62695 256

	U	
Ę	59	8

VERIFIED UTILITY INFORMATION								VERIFIED UTILITY INFORMATION										
TEST HOLE #	SIZE	& TYPE	NORTHING	EASTING	OFFSET	TOP OF UTILITY	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS	TEST HOLE #	SIZE & TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT ELEVATION	REFERENCE ELEVATION	COMMENTS	
165	24"	G	1858583.099	1177452.100	148.05 RT	-2.91'	6.08'	3.18'	SUE QUALITY LEVEL "A"						of providing and the second se			
166	24"	G	1858582.607	1177422.881	118.82 RT	-7.96'	11.04'	3.08'	SUE QUALITY LEVEL "A"									
167	24"	G	1858581.829	1177388.290	84.23 RT	-11.42'	5.64'	-5.78'	SUE QUALITY LEVEL "A"			,						
168		G	1858576.435	1177169.958	73.59 LT	-14.41'	7.92'	-6.49'										
169A		G	1858575.515	1177148.755	94.81 LT	-8.73'	5.63'	-3.10'										
169B	8"		1858574.341	1177148.755	94.81 LT	-7.34'	4.24'	-3.10'	SUE QUALITY LEVEL "A"									
170	24"	G G	1858574.341	1177125.527	118.07 LT	1.84'	4.35'	6.19'	SUE QUALITY LEVEL "A"									
171	24"	' G	1858573.831	1177107.217	136.38 LT	5.50'	5.82'	11.32'	SUE QUALITY LEVEL "A"									
172	36"	E	1859349.450	1177086.590	133.62 LT	-2.77'	10.34'	7.57'	SUE QUALITY LEVEL "A"								,	
173	36"	E	1859349.210	1177115.830	104.39 LT	-5.89'	4.92'	-0.97'	SUE QUALITY LEVEL "A"									
174		вт	1859189.980	1177120.790	104.24 LT	-13.77'	12.58'	-1.19'	SUE QUALITY LEVEL "A"									
175		вт	1859187.890	1177093.060	132.02 LT	SEE NOTE	9.12'	4.53'	CLEARANCE ONLY									
176	36"	E	1859357.690	1177382.160	100.06 RT	-11.29'	4.45'	-6.84'	SUE QUALITY LEVEL "A"									
177		E	1859358.400	1177405.990	123.90 RT	-10.32'	10.06'	-0.26'	SUE QUALITY LEVEL "A"						-			
178		T	1859198.040	1177390.570	103.95 RT	-21.35'	12.85'	-8.50'	SUE QUALITY LEVEL "A"						A LUNDON MARKET			
179		E	1859345.500	1177059.620	160.69 LT	SEE NOTE	15.15'	16.93'	CLEARANCE ONLY									
180	36"	' G	1851291.10	1177413.23	80.62 LT	-9.95	6.63	-3.32	SUE QUALITY LEVEL "A"									
181	36"	, G	1851290.85	1177418.67	75.19 LT	-9.70	6.38	-3.32	SUE QUALITY LEVEL "A"									
182	36"	' G	1851297.11	1177630.28	136.52 RT	-8.83	5.89	-2.94	SUE QUALITY LEVEL "A"									
MAN HOLE #	-																	
183	24"	' G	1851285.94	1177708.75	45.04 RT	4.76	4.16	8.92	Elev. taken from RIM of MH.									
184		' G	1851278.82	1177708.69	44.77 RT	4.39	4.52	8.91	Elev. taken from RIM of MH.							Process on Security S		
EST IOLE #	SIZE	& TYPE	NORTHING	EASTING	OFFSET	TOP OF UTILITY	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS									
185	72"	" BT	1877424.23	1176032.38	61.60 LT	-3.79	2.70	-1.09	SUE QUALITY LEVEL "A"									
186	66"	" BT	1877416.11	1175712.30	66.43 RT	-8.51	5.85	-2.66										
. ,								***************************************										
								,										
				NOTES	1		114 400 400 114 114 114 114 114 114 114											

TH #168 Unable to see gas due to ground water.
TH #169A Unable to see gas due to back fill continually caving in.

TH #174 We were unable to determine size due to ground water in the hole.

TH #175 Attempt was made to expose phone duct but were unsuccessful due to extreme heavy compacted clay, we were only able to reach 9.12'

TH #179 Attempt was made to find electric duct. Went down 15.15' & 2.5' radius of Reference Point.

TH #186 Unable to expose due to mud and ground water, felt top and sides.

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.

Illinois Department of Transportation

I-90 /94 (NB & SB of Dan Ryan Expressway)

Chicago-Cook County

Sec No: (2122-921 PT1) R, (2021-922 PTI,2)

Contract No. 62586, 62589, 62693, 62694, 62695

TBE Project No.: IL09500164, 167, 168, 170, 171, 179, 180, 182, 204, 205,

206, 211, 212, 219, 221, 225, 226, 227, 228, 230, 232, 238

REVISIONS																		
DATE	BY		BESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION
7/11/05	\$24	confoc				V differ Publicate for James and and									Andre Lake Andre Trees, about these section received about the received recommendation of the section and the			

