

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2007-9
Various Counties
Sheet 6 of 50
Contract Number 44933

District 1
Schedule of Locations for Truss Repair & Replacement

Location No.:	1-01	State I.D. No.:	1C016I290R018.8 (CLE-1)P2		
County:	Cook	Route:	I-290	M.P.:	18.8
Direction:	EB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	19.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-02	State I.D. No.:	1S016I290R020.0 (TRE-3)O4		
County:	Cook	Route:	I-290	M.P.:	20
Direction:	EB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00			
FURNISH & INSTALL HANDRAIL	Foot	47.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-03	State I.D. No.:	1C016I290R021.0 (CLE-2)N2		
County:	Cook	Route:	I-290	M.P.:	21
Direction:	EB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	21.50			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-04	State I.D. No.:	1C016I290R023.4 (C-8)L4		
County:	Cook	Route:	I-290	M.P.:	23.4
Direction:	EB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL HANDRAIL	Foot	24.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-05	State I.D. No.:	1C016I290R027.3-0 (CLE-2)H2		
County:	Cook	Route:	I-290	M.P.:	27.3
Direction:	EB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL HANDRAIL	Foot	24.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-06	State I.D. No.:	1C016I290R028.4 (CLE-1)H8		
County:	Cook	Route:	I-290	M.P.:	28.4
Direction:	EB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL HANDRAIL	Foot	35.50			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-07	State I.D. No.:	1S016I290L014.2 (TW-4)X1		
County:	Cook	Route:	I-290	M.P.:	14.2
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00			
FURNISH & INSTALL HANDRAIL	Foot	63.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-08	State I.D. No.:	1S016I290L018.0 (TRW-2)R1		
County:	Cook	Route:	I-290	M.P.:	18.0
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00			
FURNISH & INSTALL HANDRAIL	Foot	78.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-09	State I.D. No.:	1C016I290L019.4 (CLW-5)P3		
County:	Cook	Route:	I-290	M.P.:	19.4
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	19.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-10	State I.D. No.:	1C016I290L019.8 (CLW-4)O1		
County:	Cook	Route:	I-290	M.P.:	19.8
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	17.50			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-11	State I.D. No.:	1S016I290L020.7 (TRW-1)N3		
County:	Cook	Route:	I-290	M.P.:	20.7
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	2.00			
FURNISH & INSTALL HANDRAIL	Foot	43.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-12	State I.D. No.:	1S016I290L023.0 (TRW-9)L1		
County:	Cook	Route:	I-290	M.P.:	23
Direction:	WB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL HANDRAIL	Foot	56.50			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-13	State I.D. No.:	1C016I290L023.0 (CLW-3)K7		
County:	Cook	Route:	I-290	M.P.:	23
Direction:	WB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL HANDRAIL	Foot	24.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-14	State I.D. No.:	1C016I290L027.6 (CLW-2)H7		
County:	Cook	Route:	I-290	M.P.:	27.6
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	23.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-15	State I.D. No.:	1C016I290L028.7 (CLW-1)H1		
County:	Cook	Route:	I-290	M.P.:	28.7
Direction:	WB				
Description of Work	Unit	Quantity			
OVERHEAD SIGN SUPPORT GROUT REPAIR	Each	1.00			
FURNISH & INSTALL HANDRAIL	Foot	23.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-16	State I.D. No.:	1S016I090L079.6 (TW-7)		
County:	Cook	Route:	I-90	M.P.:	79.6
Direction:	WB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL SIGN BRACKET	Each	8.00			
This work shall be completed during District 1 night-time hours.					

Location No.:	1-17	State I.D. No.:	1S016I090L079.7 (TW-8)E5		
County:	Cook	Route:	I-90	M.P.:	79.7
Direction:	WB				
Description of Work	Unit	Quantity			
FURNISH & INSTALL SIGN BRACKET	Each	8.00			
This work shall be completed during District 1 night-time hours.					