



BUTT JOINT DETAIL




BITUMINOUS TRANSITION DETAIL



EXISTING PARKING LOT TYPICAL SECTION




PARKING LOT REPAIR DETAIL




EROSION CONTROL FABRIC FENCE DETAIL

NOTES

- 1. WOVEN WIRE FENCE TO BE FASTENED SECURELY TO FENCE POSTS WITH WIRE TIES OR STAPLES.
- FILTER CLOTH TO BE FASTENED SECURELY TO WOVEN WIRE FENCE WITH TIES SPACED EVERY 2'-0" AT TOP AND MID SECTION.
- 3. WHEN TWO SECTIONS OF FILTER CLOTH ADJOIN EACH OTHER THEY SHALL BE OVERLAPPED BY 6" MINIMUM AND FOLDED.
- 4. MAINTENANCE SHALL BE PERFORMED AS NEEDED AND MATERIAL REMOVED WHEN "BULGES" DEVELOP IN THE SILT FENCE. MAINTENANCE, WHICH INCLUDES THE REPLACEMENT OF DAMAGED FENCE SHALL BE CONSIDERED INCIDENTAL TO THE COST OF THE EROSION CONTROL FENCE.



DETECTABLE WARNING AT CURB RAMP



	MIN.	MAX.
D	1.60"	2.40"
E	.65"	1.50"
F	.45"	.80"
G	.90"	1.40"



TRUNCATED DOME DETECTABLE WARNING DETAIL

N.T.S.

UN044 K:\ChempaignAp\0505903\Draw\Shaets\
FILE: 30_PAVINGDETAILS.dwg LAYOUT: Layout1 UPDATE BY: jfrank SURVEY BOOK # DATE: Mon 11/21/05 11:05om XREF DWG: Cintinfo.dwg tb.dwg

REVISIONS				
NUMBER	BY	DATE		

THIS BAR IS EQUAL TO 2" AT FULL SCALE (34X22).

S

AREA DET NEOUS PARKING UNIVERSITY OF ILLINOIS WILLARD AIRPORT SCELLA Ξ REHABILITATE AND VING

CANT CANT CANT CANTORD, MARPHY & TLLY, NC. CONSULTING BNGNERS License No. 184-000613	
DESIGN BY:	CMT
DRAWN BY:	СМТ
CHECKED BY:	JEF
APPROVED BY:	SMH
DATE:	11/11/05

0505903

JOB No:

IL. PROJECT: CMI-3473

SHEET 30 OF 45 SHEETS