VERIFIED UTILITY INFORMATION								
TEST HOLE #	SIZE	& TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
109	12"	W	14039071.270	2458870.762	416.37'	5.80'	410.57	UTILITY QUALITY LEVEL "A"
110	6"	W	14039113.970	2458692.914	415.48'	3.07	412.41	UTILITY QUALITY LEVEL "A"
110A	1.5"	W	14039114.710	2458692.420	415.51	3.20'	412.31	UTILITY QUALITY LEVEL "A"
111	10"	FM	14039608.580	2457878.964	397.60'	1.94'	395.66	UTILITY QUALITY LEVEL "A"
111A	10"	FM	14039608.580	2457878.964	397.60'	3.01	394.59	UTILITY QUALITY LEVEL "A"
112	16"	FM	14044181.945	2451425.631	403.80'	2.23'	406.03'	UTILITY QUALITY LEVEL "A"
113	24"	FM	14044195.464	2451426.136	SEE NOTE	SEE NOTE	405.56'	see note
114	24"	FM	14044740.055	2451511.310	398.17'	3.56'	401.73'	UTILITY QUALITY LEVEL "A"
115	16"	FM	14044737.878	2451513.982	SEE NOTE	SEE NOTE	402.93	see note
116	16"	FM	14045312.801	2451601.700	SEE NOTE	SEE NOTE	403.44	SEE NOTE
117	24"	FM	14045315.870	2451595.033	399.70'	. 1.72"	401.42 [*]	UTILITY QUALITY LEVEL "A"
118	SEE NOTE		14045561.693	2452496.355	SEE NOTE	SEE NOTE	414.82'	SEE NOTE
119	9 SEE NOTE		14045552.786	2452466.195	SEE NOTE	SEE NOTE	414.43'	SEE NOTE
							www.monor.mom.	
							.,,.	
maimaranam					WOODEN CONTRACTOR OF THE PARTY			

*	MATION				
TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFI ELE

		<	*5			·, · · ·			
TEST HOLE #	SIZE		TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
- ' '									
	•••			- LAND WESTERNISH TO THE TOTAL THE TOTAL TO THE TOTAL TOT					
		•							
	.,,.				:				
		mimonenii							
			·						
		· · · · ·		 					
				<u> </u>					
				•					
				78					
			······································		-				
				1			L	İ.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	I.

NOTES

TEST HOLE #111 & #111A - FOUND (2) 10 PIPES ONE STACKED ON TOP OF THE OTHER, REF.

TEST HOLE #113, #115 & #116 - PIPE WAS EXPOSED ABOVE GROUND.

POINT WAS PLACED ON CENTER OF BOTH PIPES.

TEST HOLE #118 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE ONLY ABLE TO PROBE TO A DEPTH OF 15.24' AT WHICH POINT WE FELT SOMETHING SOLID BUT COULD NOT VERIFY IF IT WAS THE SEWER.

TEST HOLE #119 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE NOT ABLE TO EXCAVATE PAST 5'. NO UTILITY WAS FOUND.

ABBREVIATIONS

FM = FORCE MAIN W = WATER MAIN

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



SCALE:

REVISIONS ME DATE NAME

SUE INVESTIGATION OF UNDERGROUND UTILITIES PROJECT NO: IL09500610
VERIFIED UTILITY MATRIX

PROJECT NO: IL09500610
DATE: 7/15/10 VERIFIED UTILITY MATRIX

MISSISSIPPI RIVER BRIDGE PROJECT CONTRACT NO: D-98-061-08

DRAWN BY: KLC CHECKED BY: EG SHEET NO: 1 OF 1

1			
FILE NAME =	USER NAME :	DESIGNED EG	REVISED
\$FILEL\$		DRAWN KLC	REVISEO
	PLOT SCALE = P = 50'	CHECKED JB	REVISED
	PLOT DATE = #DATE#	DATE 9/15/09	REVISED

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

			សប	807,000,503			
EZ: "	P4 = F		F.A. RTE.	SECTION	COUNTY	TOTAL	SHEE NO.
Mississippi River I	Project			St. Cloir	29	24	
	_		PTB N	0. 147-0	038		
SHEET NO.	STA.	TO STA.	FED. RO	AD DIST. NO. ILLINOIS Job I	to. 1 0-98-061-0	В	