
CRACK ROUTING DETAIL

TRANSVERSE CRACKS
AND JOINTS AND
EDGE LINE JOINT

LONGITUDINAL SHOULDER JOINT



* HOT ASPHALT CRACK ROUTING 3/4 " x 3/4" x LENGTH OF CRACK, AS NEEDED. FIBER ASPHALT LEFT FLUSH WITH PAVEMENT.

FILE NAME =	USER NAME = leroyma	DESIGNED -			REVISED	-	11/06
c:\pw_work\PWIDOT\LEROYMA\d0149985\D570	1809-sht-details.dgn	DRAWN	-	JJB	REVISED	-	
	PLOT SCALE = 40.0000 '/ IN.	CHECKED	-		REVISED	-	
	PLOT DATE = 11/17/2009	DATE	-	7-9-09	REVISED	-	

STATI	E OF	: ILLINOIS
DEPARTMENT	OF	TRANSPORTATION

						F.A. RTE.	SECTION	COUNTY TOTAL SHEET NO.			
CRACK ROUTING DETAIL					322	2010PPP	DEWITT	11	10		
								CONTRACT	NO. 7	0809	
	SHEET NO	0F	SHEETS	STA	TO STA	CCD DO	DAD DICT NO THE INDICE CED I	ATD DROJECT			