


SOIL BORINGS

PROJECT **Box Culvert Replacement, Rockton Road over Dry Run Creek, Winn. Co., Illinois**
 CLIENT **Missman, Inc., Rockford, Illinois**
 BORING **1** DATE STARTED **8-8-12** DATE COMPLETED **8-8-12** JOB **L-78,847**
 ELEVATIONS WATER LEVEL OBSERVATIONS
 GROUND SURFACE **759.1** WHILE DRILLING **28.0'**
 END OF BORING **709.1** AT END OF BORING **28.0'**
 24 HOURS



PROJECT **Box Culvert Replacement, Rockton Road over Dry Run Creek, Winn. Co., Illinois**
 CLIENT **Missman, Inc., Rockford, Illinois**
 BORING **1** DATE STARTED **8-8-12** DATE COMPLETED **8-8-12** JOB **L-78,847**
 ELEVATIONS WATER LEVEL OBSERVATIONS
 GROUND SURFACE **769.1** WHILE DRILLING **26.0'**
 END OF BORING **709.1** AT END OF BORING **28.0'**
 24 HOURS

