

RAISED REFLECTIVE PAVEMENT MARKERS						
LOCATION	LENGTH	ONE WAY		TWO WAY AMBER	REFLECTOR REMOVAL	PRISMATIC CURB REFLECTORS
		CRYSTAL	AMBER			
GRUNDY COUNTY	FT	EACH	EACH	EACH	EACH	EACH
MEDIAN AREA AT I-55 OVERHEAD						
LOG MI. 0.031 TO 0.056	132.0	3			3	7
LOG MI. 0.056 TO 0.066	52.8	1			1	5
LOG MI. 0.066 TO 0.078	63.4				0	
LOG MI. 0.078 TO 0.082	21.1				0	
LOG MI. 0.082 TO 0.092	52.8				0	5
LOG MI. 0.092 TO 0.108	84.5				0	4
LOG MI. 0.108 TO 0.177	364.5				0	18
LOG MI. 0.177 TO 0.190	68.6				0	
IL 53 & IL 129 INTERSECTION						
SEE PLAN SHEET FOR LIMITS						
LOG MI. 0.190 TO 0.260	369.6			10	10	18
LOG MI. 0.260 TO 0.351	480.5			6	6	
LOG MI. 0.351 TO 0.408	300.96			4	4	
LOG MI. 0.408 TO 0.566	834.2			10	10	
RAILROAD BRIDGE OMISSION						
LOG MI. 0.566 TO 0.622	295.7			8	8	
LOG MI. 0.622 TO 0.736	601.9			6	6	
LOG MI. 0.736 TO 0.831	501.6			76	76	
LOG MI. 0.831 TO 1.982	6077.3			11	11	
LOG MI. 1.982 TO 2.148	876.5			69	69	
LOG MI. 2.148 TO 3.187	5485.9			13	13	
LOG MI. 3.187 TO 3.389	1066.5					
SN 032-0023 OVER MAZON RIVER BRIDGE OMISSION						
LOG MI. 3.389 TO 3.430	216.5			23	23	
LOG MI. 3.430 TO 3.781	1853.3			70	70	
LOG MI. 3.781 TO 4.840	5591.52					
BRACEVILLE RD. INTERSECTION						
SEE PLAN SHEET FOR LIMITS						
LOG MI. 4.840 TO 4.896	295.7		15		15	
LOG MI. 4.896 TO 4.930	177		9		9	
LOG MI. 4.930 TO 4.983	279.8	6		8	14	18
LOG MI. 4.983 TO 5.013	158.4		8		8	
LOG MI. 5.013 TO 5.028	79.2		3		3	
LOG MI. 5.028 TO 5.076	253.4		13		13	
LOG MI. 5.076 TO 6.440	7201.9			90	90	
TOTAL	33837.1	10	48	404	462	75

PATCHING SCHEDULE GARDNER TO GRUNDY/WILL COUNTY LINE							
LOG MILE	OFFSET LEFT/RIGHT	WIDTH	LENGTH	TYPE II	TYPE III	TYPE IV	DESCRIPTION
				SQ YD	SQ YD	SQ YD	
0.2	LEFT	13	6	8.7			REFLECTIVE CRACK
0.2	RIGHT	13	6	8.7			REFLECTIVE CRACK
0.67	LEFT	21	30			70	HEAVE
2	LEFT	16	12		21.3		ABOVE CULVERT
2	RIGHT	16	12		21.3		ABOVE CULVERT
2.4	LEFT	13	10	14.4			SETTLEMENT
2.4	RIGHT	13	10	14.4			SETTLEMENT
4.6	RIGHT	13	6	8.7			REFLECTIVE CRACK
4.7	LEFT	13	6	8.7			REFLECTIVE CRACK
4.7	RIGHT	13	6	8.7			REFLECTIVE CRACK
4.8	LEFT	13	6	8.7			REFLECTIVE CRACK
4.8	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.1	LEFT	13	6	8.7			REFLECTIVE CRACK
5.1	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.3	LEFT	13	6	8.7			REFLECTIVE CRACK
5.3	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.6	LEFT	13	6	8.7			REFLECTIVE CRACK
5.6	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.65	LEFT	13	6	8.7			REFLECTIVE CRACK
5.65	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.75	LEFT	13	6	8.7			REFLECTIVE CRACK
5.75	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.8	LEFT	13	6	8.7			REFLECTIVE CRACK
5.8	RIGHT	13	6	8.7			REFLECTIVE CRACK
5.9	LEFT	13	6	8.7			REFLECTIVE CRACK
5.9	RIGHT	13	6	8.7			REFLECTIVE CRACK
6	LEFT	13	6	8.7			REFLECTIVE CRACK
6	RIGHT	13	6	8.7			REFLECTIVE CRACK
6.08	LEFT	13	6	8.7			HEAVE
6.08	RIGHT	13	6	8.7			HEAVE
6.12	LEFT	13	6	8.7			REFLECTIVE CRACK
6.12	RIGHT	13	6	8.7			REFLECTIVE CRACK
6.2	RIGHT	13	6	8.7			REFLECTIVE CRACK
TOTAL				272	43	70	