
ROUTE NO.	SECTION	COUNTY ST. CLAIR		TOTAL SHEETS	SHEET NO.
F.A.I. 70	*			99	91
FED. ROAD DIST.	. NO. 7	ELLINGIS	FED. AID PR	0.JFCT- LM-70	

\* 82-3HVB-3R-5 CONTRACT NO. 76985

SHEET \$-14 OF S-22





PLAN

## INFRARED THERMOGRAPHIC INSPECTION RESULTS

FIELD OBSERVATIONS SUMMARY		TOPS	IDE	LEGEND	
ITEM	UNIT	QUANT.	%	DELAMINATION	
TOTAL AREA	ft2	3981		SPALL	
SHADE/DEBRIS	f†²	0		DEBOND	ATTITITION
DELAMINATION	f†²	108	2.7		
SPALL	ft <sup>2</sup>	0	0	ASPHALT PATCH	
DEBOND	f +2	872	21.9	SUBSURFACE PATCH	
ASPHALT PATCH	f t <sup>2</sup>	0	0	SHADE/DEBRIS	07777
SUBSURFACE PATCH	f t²	0	0	SHAUE/ DEDRIS	VIII



## ANTICIPATED DECK REPAIR QUANTITIES (ft.2)

SPAN	2000 SURVEY RESULTS	2007 ANTICIPATED PARTIAL DEPTH REPAIRS
T5	270	380
T6	220	300

OUANTITIES IN THIS TABLE ARE FOR INFORMATIONAL PURPOSES ONLY AND ARE INCLUDED UNDER THE BRIDGE DECK HYDRO-SCARFICATION AND BRIDGE DECK MICROSILICA CONCRETE OVERLAY PAY ITEMS, REFER TO SPECIAL PROVISIONS.

## NOTES:

WISS, JANNEY, ELSTNER ASSOCIATES, INC. CORE LOCATIONS DESIGNATED AS "WJE". EARTH TECH, INC. CORE LOCATIONS DESIGNATED AS 'ET'.

AREAS OF DECK DELAMINATIONS AND SPALLS SHOWN REQUIRING REPAIR ARE ESTIMATED. ACTUAL REPAIR LOCATIONS SHOULD BE SHOWN ON AS-BUILT DRAWINGS.

INFRARED INSPECTION DATE: 7/24/00-7/26/00 SURFACE TYPE: ASPHALT OVERLAY

## INFRARED THERMOGRAPHIC INSPECTION RESULTS

	1/1///	ANLU	THENWOONATHE INSTECTION RESULTS	
	REVISIONS		STATE OF ILLINOIS	
EARTH STECH	NAME	DATE	DEPARTMENT OF TRANSPORTATION REHABILITATION AND RETROFIT REPAIRS	
			FAI ROUTE 70	
		PRIVATA PRIVATA AND SALES	POPLAR STREET BRIDGE APPROACHES	
			ST, CLAIR COUNTY	
INSPECTED: TC CADD: MA/M			STRUCTURE NO. 082-0146 (Ramp T)	
DS/EG	1		SCALE: N.T.S.	
ANALYSIS: TC CHECKED: DU			DATE: 02/01/2007	

TILENAME: 1242007

FILENAME: 1242007

FILENAME: P./20

GHECKED DESIGNED ---/MA

DESIGNED --

adwayRehab\_AT\RampT\Earth\_Tech\T\_ET0506.dgn