TOTAL SHEET NO. F.A.I. 70 ST. CLAIR 111 44 FED. ROAD DIST. NO. 7

* 82-3HVB-3R-3

SHEET S-21 OF S-44

CONTRACT NO. 76305

192'-4" END TO END CURB ALONG & HAN.	DRAIL POSTS
© PIER D38	© PIER D39 WJE
100'-6" SPAN D38	91'-9" SPAN D39
192'-1" END TO END CURB ALO.	NG & RUADWAI D



PLAN

INFRARED THERMOGRAPHIC INSPECTION RESULTS

FIELD OBSERVATIONS SUMMARY		TOPSIDE		LEGEND		
ITEM	UNIT	QUANT.	%	DELAMINATION		
TOTAL AREA	f†²	9227		SPALL		
SHADE/DEBRIS	f +2 f +2	0		DEBOND		
DELAMINATION		56	0.6			
SPALL	f †²	0	0	ASPHALT PATCH		
DEBOND	f †2	242	2.6	SUBSURFACE PATCH		
ASPHALT PATCH	f t2	0	0	SHADE/DEBRIS	77777	
SUBSURFACE PATCH	f†²	0	0	21 MOE / DEDUIS	MILL	



ANTICIPATED DECK REPAIR QUANTITIES (ft.2)

SPAN	2000 SURVEY RESULTS	2005 ANTICIPATED PARTIAL DEPTH REPAIRS
D38	220	280
D39	190	240

QUANTITIES IN THIS TABLE ARE FOR INFORMATIONAL PURPOSES ONLY AND ARE INCLUDED UNDER THE BRIDGE DECK HUPRO-SCARFICATION AND BRIDGE DECK MICROSLICA CONCRETE OVERLAY PAY ITEMS. REFER TO SPECIAL PROVISIONS.

NOTES:

WISS, JANNEY, ELSTNER ASSOCIATES, INC. CORE LOCATIONS DESIGNATED AS "WJE". EARTH TECH, INC. CORE LOCATIONS DESIGNATED AS "ET".

AREAS OF DECK DELAMINATIONS AND SPALLS SHOWN REQUIRING REPAIR ARE ESTIMATED. ACTUAL REPAIR LOCATIONS SHOULD BE SHOWN ON AS-BUILT DRAWINGS.

INFRARED INSPECTION DATE: 7/24/00-7/26/00 SURFACE TYPE: ASPHALT OVERLAY

INFRARED THERMOGRAPHIC INSPECTION RESULTS

										1NF	RAKED	THERMUGH				
													REVISIONS			
	E	A	R	T	Н	(E)	T	E C	Н	NAME	DATE	DI REHA				
												POF				
	INSPEC	TED	TC					CADDs	MA/MD DS/EG			STRUCTURE NO. 0				
	ANALY:	SIS:	TC					CHECKED:	DU			SCALE:				
												DATE: 02/28/200				

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION HABILITATION AND RETROFIT REPAIRS FAI ROUTE 70 OPLAR STREET BRIDGE APPROACHES ST. CLAIR COUNTY

. 082-0142 (RAMP S)

MRS. pr\2001\1201-1300\2001.1240\\drafting\roadwayrehab_ds\rampd\earth tech\d_et3839.dgn PATE: 41928
FILENAME:
CHECKED
CHECKED CSD CLK JPD