

* 113(RS-5,BR) & 114RS-2 ** CHAMPAIGN & VERMILION CONTRACT NO. 90864


DETAIL OF BITUMINOUS SURFACE REMOVAL - BUTT JOINT

 STATION
 67+39.00
 TO
 STATION
 67+84.00

 STATION
 70+76.00
 TO
 STATION
 71+21.00

 STATION
 120+55.00
 TO
 STATION
 121+00.00

 STATION
 126+00.00
 TO
 STATION
 126+45.00



DETAIL OF BITUMINOUS SURFACE REMOVAL - BUTT JOINT

STATION 9+51.94 TO STATION 9+36.94 (PARK AVE.)
STATION 802+68.00 TO STATION 802+98.00 (PENNFIELD RD.)
STATION 804+66.00 TO STATION 804+96.00 (PENNFIELD RD.)

