VERIFIED UTILITY INFORMATION TEST HOLE # EXISTING COMMENTS SIZE & TYPE NORTHING EASTING TOP ELEVATION ELEVATION 5.80' 2458870.762 416.37 410.57 UTILITY QUALITY LEVEL "A" 109 14039071.270 110 6" 14039113.970 2458692.914 415.48 3.07 412.41 UTILITY QUALITY LEVEL "A" 412.31 110A 1.5" W 14039114.710 2458692.420 3.20 UTILITY QUALITY LEVEL "A" 415.51 10" FM 14039608.580 2457878.964 395.66 UTILITY QUALITY LEVEL "A" 111 397.60' 1,94 111A 10" 14039608.580 2457878.964 394.59 FΜ 397.60' 3.01 UTILITY QUALITY LEVEL "A" 112 FM 14044181.945 2451425.631 406.03 16" 403.80 2.23 <u>UTILITY QUALITY LEVEL "A"</u> 14044195.464 2451426.136 405.56 FM 113 24" SEE NOTE SEE NOTE SEE NOTE 114 FM 14044740.055 2451511.310 401.73 24" 398.17 3.56 <u>UTILITY QUALITY LEVEL "A"</u> FΜ 14044737,878 115 16" 2451513.982 SEE NOTE SEE NOTE 402.93 SEE NOTE 14045312.801 2451601.700 SEE NOTE SEE NOTE 403.44 SEE NOTE 116 16" FΜ 117 14045315.870 2451595.033 401.42* 24" FM 399.70 1.72 UTILITY QUALITY LEVEL "A" 14045561.693 2452496.355 414.82 SEE NOTE 118 SEE NOTE SEE NOTE SEE NOTE SEE NOTE 119 14045552.786 2452466.195 SEE NOTE SEE NOTE 414.43 SEE NOTE

TEST OLE #		&	TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
							·		
									The state of the s
	O-MANAGEMENT WITH THE						***************		
			·	i + 4.4.4.4					
	~~~~								
		***************************************	**********		A CONTRACTOR CAST (ATTENT) - ATTENT				
									***************************************
		***************************************							***************************************
							MATRICULAR PROGRAMMENT OF THE PR	., .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
								-	
				-	, , , , , , , , , , , , , , , , , , , ,				
	document with wind with the contract of the co								
							,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
									,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	***************************************								
								·	
									Manager Company of the Company of th
				*	-				
1									

NOTES

TEST HOLE #111 & #111A - FOUND (2) 10° PIPES ONE STACKED ON TOP OF THE OTHER, REF. POINT WAS PLACED ON CENTER OF BOTH PIPES.

TEST HOLE #113, #115 & #116 - PIPE WAS EXPOSED ABOVE GROUND.

TEST HOLE #118 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE ONLY ABLE TO PROBE TO A DEPTH OF 15.24' AT WHICH POINT WE FELT SOMETHING SOLID BUT COULD NOT VERIFY IF IT WAS THE SEWER.

TEST HOLE #119 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE NOT ABLE TO EXCAVATE PAST 5'. NO UTILITY WAS FOUND.

**ABBREVIATIONS** FM = FORCE MAIN

W = WATER MAIN

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



SCALE:

REVISIONS					
NAME	DATE				

SUE INVESTIGATION OF UNDERGROUND UTILITIES VERIFIED UTILITY MATRIX

> MISSISSIPPI RIVER BRIDGE PROJECT CONTRACT NO: D-98-061-08

S	PROJECT NO:
.5	JL09500610
	DATE: 7/15/10
	DRAWN BY: KLC
	CHECKED BY: EG
	SHEET NO:
	1 0F 1

COUNTY TOTAL SHEET SHEETS NO.

St. Cloir 38 31

FILE NAME =	USER NAME :	DESIGNED	EG	REVISED
SFILELS		DRAWN	KLC	REVISEO
	PLOT SCALE + P = 50'	CHECKED	JB	REVISED
	PLOT DATE = #DATE#	DATE	9/15/09	REVISED

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** 

bullet					857,			
*** * = * Pa*		M-1-1		F.A. RTE.	SECTION	COUNTY	10 5H	
Mississippi River Bri			Project			St. Cloir		
				_	PTB NO			
	SHEET NO.	STA,	TO STA.	FED. R	DAD DIST., NO. [ILLINOIS] Job I	No., 0-98-061-0	36	