VERIFIED UTILITY INFORMATION								
TEST HOLE #	SIZE	& TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
109	12"	W	14039071.270	2458870.762	416.37	5.80'	410.57	UTILITY QUALITY LEVEL "A"
110	6"	W	14039113.970	2458692.914	415.48'	3.07'	412.41	UTILITY QUALITY LEVEL "A"
110A	1.5"	W	14039114.710	2458692.420	415.51	3.20'	412.31	UTILITY QUALITY LEVEL "A"
111	10"	FM	14039608.580	2457878.964	397.60'	1,94'	395.66	UTILITY QUALITY LEVEL "A"
111A	10"	FM	14039608.580	2457878.964	397.60'	3.01	394.59	UTILITY QUALITY LEVEL "A"
112	16"	FM	14044181.945	2451425.631	403.80'	2.23	406.03'	UTILITY QUALITY LEVEL "A"
113	24"	FM	14044195.464	2451426.136	SEE NOTE	SEE NOTE	405.56'	see note
114	24"	FM	14044740.055	2451511.310	398.17'	3.56'	401.73'	UTILITY QUALITY LEVEL "A"
115	16"	FM	14044737.878	2451513,982	SEE NOTE	SEE NOTE	402.93	see note
116	16"	· FM	14045312.801	2451601.700	SEE NOTE	SEE NOTE	403.44	see note
117	24"	FM	14045315.870	2451595.033	399.70'	. 1.72	401.42	UTILITY QUALITY LEVEL "A"
118	SEE NOTE		14045561.693	2452496.355	SEE NOTE	SEE NOTE	414.82'	see note
119	SEE NOTE		14045552.786	2452466.195	SEE NOTE	SEE NOTE	414.43'	see note
				·	}			
							WINDLO CONTROL OF THE PROPERTY	
				and the second				
· · · · · · · · · · · · · · · · · · ·								
				1				

) 	VERIFIED UTILITY INFORMATION						
TEST HOLE #	SIZE		TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS	
NAME OF THE OWNER, WE WANT TO THE	• Section of the section of	(I)						MILLEMANUS PROPERTY OF THE STATE OF THE STAT	L. L	
	*******************	**********	***************************************							
							,			
	/100/00/10/00/10/10/10/10/10/10/10/10/10	ara imzormi								
***************************************		* ut., ** ***						\$1.000 to \$1.000		

			on the second se							
			·							
						A STATE OF THE STA			M	
								,		
			y egy							
		ununerrene				L. L. MININIA			THE STATE OF THE S	
			CONTRACTOR STATE	•						
				38						

NOTES

ABBREVIATIONS

TEST HOLE #111 & #111A - FOUND (2) 10° PIPES ONE STACKED ON TOP OF THE OTHER, REF. POINT WAS PLACED ON CENTER OF BOTH PIPES.

FM = FORCE MAIN W = WATER MAIN

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.

TEST HOLE #113, #115 & #116 - PIPE WAS EXPOSED ABOVE GROUND.

TEST HOLE #118 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE ONLY ABLE TO PROBE TO A DEPTH OF 15.24' AT WHICH POINT WE FELT SOMETHING SOLID BUT COULD NOT VERIFY IF IT WAS THE SEWER.

TEST HOLE #119 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE NOT ABLE TO EXCAVATE PAST 5'. NO UTILITY WAS FOUND.

Cardno TBE

REVISIONS NAME DATE

SUE INVESTIGATION OF UNDERGROUND UTILITIES PROJECT NO: VERIFIED UTILITY MATRIX MISSISSIPPI RIVER BRIDGE PROJECT CONTRACT NO: D-98-061-08

IL09500610
DATE: 7/15/10
DRAWN BY: KLC
CHECKED BY: EG
SHEET NO:
1 OF 1

1					l
FILE NAME =	USES NAME 4	DESIGNED	EG	REVISED	
\$FILEL\$		DRAWN	KLC	REVISEO	
	PLOT SCALE = P = 50'	CHECKED	JB	REVISED]
	PLOT DATE = #STACE#	DATE	9/15/09	REVISED	<u> </u>

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

			~~~~~~				DITUNUTAN	
Mark Marie (Mark - Mark - M	X 22 " " " "		B	F.A.T. RTE.	SECTION	COUNTY		SHEET NO.
	Mississippi Rive	er Briage	Project			St. Clofr	37	28
			-			PTB N	0. 147-0	38
CALE:	SHEET NO.	STA.	TO STA.	FEQ. ROA	D DIST. NO.   ILLINOIS Job 1	No.: 0-98-061-0	8	