


BORING LOG 03-RWB-02


WEI Job No.: 1100-04-01
 Client: AECOM
 Project: Circle Interchange Reconstruction
 Location: Section 17, T39N, R14E of 3rd PM
 Datum: NAVD 88
 Elevation: 593.70 ft
 North: 1898142.33 ft
 East: 1170680.34 ft
 Station: 1839+83.93
 Offset: 38.8940 RT



GENERAL NOTES		WATER LEVEL DATA	
Begin Drilling	08-22-2013	Complete Drilling	08-23-2013
Drilling Contractor	Wang Testing Services	Drill Rig	D-25 ATV
Driller	P&R	Logger	F. Bozga
Checked by	C. Marin	Drilling Method	2.25" HSA to 15', mud rotary thereafter, boring grouted upon completion
White Drilling	13.00 ft	At Completion of Drilling	NA
Time After Drilling	NA	Depth to Water	NA

BORING LOG 03-RWB-03


WEI Job No.: 1100-04-01
 Client: AECOM
 Project: Circle Interchange Reconstruction
 Location: Section 17, T39N, R14E of 3rd PM
 Datum: NAVD 88
 Elevation: 595.15 ft
 North: 1898142.41 ft
 East: 1170611.57 ft
 Station: 1840+52.56
 Offset: 43.2853 RT



GENERAL NOTES		WATER LEVEL DATA	
Begin Drilling	08-19-2013	Complete Drilling	08-21-2013
Drilling Contractor	Wang Testing Services	Drill Rig	D-25 ATV
Driller	P&N	Logger	F. Bozga
Checked by	C. Marin	Drilling Method	2.25" HSA to 15', mud rotary thereafter, boring grouted upon completion
White Drilling	NA	At Completion of Drilling	NA
Time After Drilling	NA	Depth to Water	NA

BORING LOG 03-RWB-03

WEI Job No.: 1100-04-01
 Client: AECOM
 Project: Circle Interchange Reconstruction
 Location: Section 17, T39N, R14E of 3rd PM
 Datum: NAVD 88
 Elevation: 595.15 ft
 North: 1898142.41 ft
 East: 1170611.57 ft
 Station: 1840+52.56
 Offset: 43.2853 RT



GENERAL NOTES		WATER LEVEL DATA	
Begin Drilling	08-19-2013	Complete Drilling	08-21-2013
Drilling Contractor	Wang Testing Services	Drill Rig	D-25 ATV
Driller	P&N	Logger	F. Bozga
Checked by	C. Marin	Drilling Method	2.25" HSA to 15', mud rotary thereafter, boring grouted upon completion
White Drilling	NA	At Completion of Drilling	NA
Time After Drilling	NA	Depth to Water	NA