CONTRACT. NO. S

60003

VERIFIED UTILITY INFORMATION								VERIFIED UTILITY INFORMATION											
EST OLE #	SIZE & TYPE	NORTHING	EASTING	STATION	OFFSET	TOP OF UTILITY ELEVATION	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS	TEST HOLE #	SIZE & TYPE	NORTHING	EASTING	STATION	OFFSET	TOP OF UTILITY ELEVATION	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS
1	12" Wide BT	1920303.68	1120229.32	100+21.396	52.32 LT		4.31	627.99'	UTILITY QUALITY LEVEL "A"								4		
2	12" W	1920287.79		100+21.938			4.45'	628.09	UTILITY QUALITY LEVEL "A"										
2A	4" G	1920286.52		100+22.002			3.10'	628.08'	UTILITY QUALITY LEVEL "A"										
3		1920281.67		100+21.861			10.56	628.13'	UTILITY QUALITY LEVEL "A"										
4	4" G	1920210.89	1120233.34	<u> </u>			2.84'		UTILITY QUALITY LEVEL "A"										
5	4" G	1920208.33	 				3.08'	628.23'	UTILITY QUALITY LEVEL "A"										
6	10" W	1920218.46	 	101+15.854	1	1	4.88'	628.16'	UTILITY QUALITY LEVEL "A"										
7	See Notes E	1920227.32		101+16.031			4.74'	627.52'	UTILITY QUALITY LEVEL "A"										
8	10"x12" BT	1920223.25					2.60'	627.74	UTILITY QUALITY LEVEL "A"										
	~																		***
				157															
				:															
																		- 7	
			ļ																
					-														
											4/*********************************								
				:															
				1	NIC	DTES							<u> </u>					FOR	
																	/ /ì	FORMA	- TIDA (
Ē (est Hole	#7 - T	BE found					d pipes. W	ithin test								_//\	FUKIVIA.	11014

Test Hole #7 - TBE found (2) 4" steel, rubber coated pipes. Within test hole a third line was found in between the (2) 4" pipes that appears to be larger, but was unable to measured due to configuration of the pipes. It was also coated in unknown material.

 \bigcirc

ALL INFORMATION SHOWN WAS OBTAINED FROM A

LOCATION SURVEY. OFFSETS AND STATIONS ARE

IN RELATION TO THE BASELINE OF SURVEY.

Illinois Department of Transportation

Belmont Avenue at Plainfield Avenue River Grove, Cook Co. IL Section No. 0406WRS Contract No. 60C03 TBE Project No.: IL09500268, 275

					·			l l		
			REVI	\ N \						*** D. C
			11			THE STATE OF THE S	DESCRIPTION DATE BY	DECEDIBLION 1		TRF
	TO LOT LOT	DECORPORATION INVESTIGATION	DECODIDATION	I DAIF BY I	DESCRIPTION	I DATE I BY I	DESCRIPTION TOATED BY	DESCRIPTION F		1 6 6
I DATE BY I DESC	RIPLIUN LUALELDI I	DESCRIPTION DATE D	DESCRIPTION		DESCRIÇÃO I A SIA		9 4 9 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		C*	IVII ENGINEERING
1.07.1.2.1.0.1	**************************************									TITE CHOTHERITING
			1	1 1 1		1 1 1		1		# PLANNING #
l i		1 1	•	1 1 1		1 1	I I I	1	201100	
1 1	1 1 1	i l	1	1 1			1 1			
1 1 1		i i				1 1	, ,			



VERIFIED
UTILITY
LOCATIONS