

ROUTE	SECTION	COUNTY	TOTAL SHEETS	SHEET NUMBER
VARIOUS	2012-042-I	COOK	20	8

CONTRACT: 60V31

LOCATION	COMB. CONC. C & G R&R (LF)	HMA SURF R&R VARIABLE DEPTH (SQYD)	SALT TOLERANT SODDING (SQYD)	SIDEWALK 5" R&R (SQFT) 18" CARRIAGE/ COURTESY	SIDEWALK 5" R&R (SQFT) 6' PARALLEL	SIDEWALK 8" R&R (SQFT) 6' PARALLEL	DRIVEWAY 8" R&R (SQFT)	DETECTABLE WARNINGS (ADA RAMPS) (SQFT)	REMARKS
3630 West 70th Street	30.0	5.0	3.4	15.0	0.0	0.0			Replace 30 Feet of Curb and Gutter In Front of Entire Length of Home
3634 West 70th Street	30.0	5.0	3.4	15.0	0.0	0.0			Replace 30 Feet of Curb and Gutter In Front of Entire Length of Home
3901 West 70th Street	20.0	3.4	3.4	0.0	0.0	0.0			Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind This Address (PUT BACK EXISTING LANDSCAPE)
3944 West 70th Street	20.0	3.4	3.4	0.0	0.0	30.0		10.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind This Address
3945 West 70th Street	20.0	3.4	3.4	0.0	0.0	30.0		10.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind This Address
3803 West Marquette Road/3800 West 67th Place	40.0	6.7	0.0	0.0	0.0	60.0	40.0	20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
3859 West Marquette Road/3858 West 67th Place	40.0	6.7	3.4	0.0	0.0	60.0	40.0	20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
3901 West Marquette Road/3900 West 67th Place	40.0	6.7	2.0	0.0	0.0	60.0	56.0	20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
3757 West Marquette Road/6715 South Hamlin Avenue	40.0	6.7	3.4	0.0	0.0	60.0		20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
4025 West Marquette Road/6715 South Komensky Avenue	40.0	6.7	3.4	0.0	0.0	60.0	30.0	20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
6048 South Austin Avenue		0.0	0.0	0.0	30.0	0.0			Replace 1 Sidewalk Square
6052 South Austin Avenue	10.0	1.7	1.7	0.0	0.0	0.0			Repair Curb and Gutter In Front of This Address
6419 South Austin Avenue	30.0	5.0	1.7	30.0	0.0	0.0			Replace Courtesy Walk, and 30 Feet of Curb and Gutter in front of home. It is currently too high and too deep, and is causing a standing water issue.
6423 South Austin Avenue	0.0	0.0	0.0	0.0	60.0	0.0			Repair Caving-In Cement/Concrete In Front of This Address
6435 South Austin Avenue		0.0	0.0	0.0	180.0	0.0			Replace 6 Cracked Sidewalk Squares and 2 ADA Ramps
7200 South Avers	7.0	1.2	1.2	0.0	0.0	0.0			Replace 7 Feet of Missing Gutter on Either Side of Adjacent Sewer Catch Basin on 72nd Street Side
7158 South Avers Avenue/7159 South Springfield Avenue	40.0	6.7	0.0	0.0	0.0	60.0	60.0	20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
7200 South Avers Avenue/7201 South Springfield Avenue	40.0	6.7	6.7	0.0	0.0	60.0		20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
7114 South Central Park Avenue	20.0	3.4	0.0	0.0	60.0	0.0		20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Next To This Address
7158 South Central Park Avenue/7159 South Millard Avenue	40.0	6.7	6.7	0.0	0.0	60.0		20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
7200 South Central Park Avenue/7201 South Millard Avenue	40.0	6.7	0.0	0.0	0.0	60.0		20.0	Repair Alley Return/Apron In its Entirety With Concrete and ADA Ramps Behind These Two Listed Addresses That Share This Alley Return/Apron
6545 South Hamlin Avenue	20.0	3.4	0.0	60.0	1200.0	0.0	30.0		Replace 40 Front and Side Sidewalk Squares, 2 Front and 1 Side Courtesy Walks, 21 Carriage Walk Squares, and 1 Side Driveway Apron
SUB-TOTAL	567.0	95.2	47.2	120.0	1530.0	600.0	256.0	220.0	

ILLINOIS DEPARTMENT OF TRANSPORTATION
SCHEDULE OF QUANTITIES