| ROUTE | SECTION | COUNTY | TOTAL SHEETS | SHEET NUMBER | | |
|---------|------------|---------|--------------|--------------|--|--|
| VARIOUS | 2009-071 I | VARIOUS | 18 | 16 | | |

CONTRACT 60H79

| | | · | | · · · · · · · · · · · · · · · · · · · | · | · | · | , | | | | · | | T | · | , | | _ |
|--------------|---------------------|-----------------------------|-----------------------------|---------------------------------------|------------|------------|------------|----------------|--|-------------------------------|---------------------|--------------|----------|---|--------|-----------------------------------|-----------------------|---|
| Sheet | Virginia Creeper | Trumpet Vine - Orange | Stella d' Oro Daylily | Turf Restoration | 2" Topsoil | 4" Topsoil | 6" Topsoil | 12" Topsoil | Nutrients · | Erosion Control Blanket | Modified Seeding | Round- up | Trees | type of tree | Shrubs | type of shrub | Selective Clearing | Location |
| 18 | 0 | Ording C | 0 | 0.08 | 368 | 0 | 0 | 0 | 7.2 | 368 | 0 | 0 | 0 | | 0 | | 0 | area s/o 79th St |
| 19 | 0 | 0 | 0 | 0.023 | 0 | 108 | 0 | 0 | 2.07 | 108 | 0 | 0.023 | 0 | | 0 | | 0 | along 79th St exit ramp |
| | | | | 1 | _ | | | | , | | _ | | • | | | | | along 76th St entrance ramp (vines and daylilies |
| 20 | 0 | 0 | 0 | 0.002 | 0 | 0 | 0 | 8 | 0.18 | 8 | 0 | 0 | 0 | | 0 | | 0 | interplanted w/in existing bed; turf restoration just s/o |
| | 0 | 0 | 0 | 0.011 | 54 | 0 | 0 | 0 | 0.99 | 54 | 0 | 0 | 0 | | 0 | | 0 | between 76th St and 75th St |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | _ | 17 | 17 - miss kim manchurian lilac | 0 | around HMLT near AIS |
| 24 | 0 | 0 | 0 | 0.12 | 0 | 445 | 0 | 0 | 10.8 | 535 | 0 | 0 | 0 | | 0 | | 0 | area n/o 75th St |
| 1 | 0 | 0 | 0 | 0.1 | 0 | 250 | 0 | 0 | 9 | 469 | 0 | 0 | 0 | | 0 | | 0 | area s/o 67th St |
| 26,27 | 0 | 0 | 0 | 0.12 | 0 | 62 | 0 | 0 | 10.8 | 552 | 0 | 0 | 0 | · | 0 | , | 0 | install vines at north end of exisiting bed; install daylilies in front of vine bed; seeding behind back of |
| 28,29 | 0 | 0 | . 0 | 0.08 | 0 | 309 | 0 | 0 | 7.2 | 309 | 0 | 0 | 0 | | 0 | | 0 | area s/o CRI & P RR |
| 28,29 | <u> </u> | <u> </u> | 1 | 0.08 | | 303 | <u> </u> | <u> </u> | 7.4 | 303 | L | | · | | | L | | jarea 3/0 Citi & Fitt |
| 30 | 0 | 0 | Ι ο | 0.02 | 37 | 0 | 0 | 0 | 1.8 | 37 | 0 | 0 | 0 | | 0 | | 0 | area s/o 63rd St |
| 31 | 0 | 0 | 0 | 0.02 | 0 | 23 | 0 | 0 | 0.9 | 46 | 0 | 0.01 | 0 | | 0 | | 0 | area just s/o CRI & P RR |
| 21 | 0 | 0 | 0 | 0.01 | 0 | 368 | 0 | 0 | 7.2 | 368 | 0 | 0.01 | 0 | | 0 | | 0 | area just n/o CRI & P RR |
| | 0 | 0 | 0 | 0.04 | 192 | 0 | 0 | 0 | 3.6 | 58 | 0 | 0 | 0 | | 0 | ······ | 0 | area surrounding HMLt @ station 3431 + 50 |
| | 0 | 0 | 0 | 0.04 | 184 | 0 | 0 | 0 | 3.6 | 184 | 0 | 0 | 0 | | 0. | | 0 | area surrounding sign truss @ station 3434 + 50 |
| 32 | 0 | 0 | 0 | 0.05 | 187 | 0 | 0 | 0 | 4.5 | 212 | 0 | 0.04 | 0 | | 0 | | 0 | area s/o CTA Green Line |
| 32 | 0 | . 0 | 0 | 0.001 | 0 | 0 | 0 | 0 | 0.09 | 5 | 0 | 0.04 | 0 | | 23 | 23 - Gro Low Sumac | 25 | area between CTA Green Line and s/o 59th St |
| | | | ļ | 0.07 | 225 | 0 | 0 | 0 | 6.3 | 335 | 0 | 0 | 0 | | 0 | Sullac | - 23 | In to FOth Ct to to HAMIT |
| L | 0 | 0 | 0 | 0.07 | 335 | <u> </u> | <u> </u> | U | 0.5 | 333 | <u> </u> | 1 0 | <u> </u> | | 1 | l | | n/o 59th St (n/o HMLT) |
| 38 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 · | 0 | 0 | 0 | 0 | 0 | | 0 | | 0 | 51st St bridge abutment - s/o |
| | 0 | 0 | 0 | 0 | 0 | 0 | . 0 | 0 | 0 | 0 | 0 | 0. | 5 | 4 - Swamp White Oak & 1 - Red Jewel Crabapple | 0 | · | 0 | s/o HMLT (station: 3511 + 50 to 3512 + 25) |
| 40,41 | 0 | 0 | 0 | 0.02 | 43 | 0 | 0 | 0 | 1.8 | 43 | 0 | 0 | 0 | | 0 | | 0 | area s/o 47th St |
| 42 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 334 | 0.07 | 0.07 | 0 | | 0 | | 0 | vines & daylilles interplanted w/in existing vine/daylily bed; extend existing seeded area near 45th St |
| 44 | 0 | 0 | 0 | 0.03 | 28 | 0 | 0 | 0 | 2.7 | 101 | 0 | 0 | 0 | | 0 | | 0 | area n/o 43rd St |
| | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | .0 | 0 | 0 | 3 | 3 - Swamp White Oak | 0 | | 0 | s/o 42nd St bridge abutment |
| | | · | · | · | · | γ | r | | ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ | | r | ₁ | | r | · | r | | ~ |
| 45 | . 0 | . 0 | 0 | 0.003 | 0 | 0 | . 0 | 9 | 0.27 | 9 | 0 | 0 | 0 | | 0 | | 0 | between Root St and CRI & P RR (Station: 3572 + 00) |
| 46 | 0 | 0 | 0 | 0.04 | 0 | 0 . | 0 | 0 | 3.6 | 167 | 0 | 0 | 0 | | 0 | | 0 | along Pershing Rd entrance ramp |
| | 0 | 0 | 0 | 0.01 | 0 | 0 | 0 | 0 | 0.9 | 34 | 0.01 | 0.01 | 0 | | 0 | | 0 | s/o Pershing Rd |
| | 0 | 0 | 0 | 0.007 | 32 | 0 | 0 | 0 | 0.63 | 32 | 0.05 | 0.05 | 5 | 5 - Catalpa | 0 | | 0 | n/o Pershing Rd |
| 47 | 0 : | 0 | 0 | 0.004 | 0 | 17 | 0 | 0 | 0.36 | 17 | 0 | 0 | 14 | 7 - Clump Form Kentucky Coffeetree & 7 China Snow Peking Lilac | 0 | | 0 | s/o 37th St |
| 50 | 0 | 0 | 0 | 0.0002 | 0 | 0 | 0 | 1 | 0.018 | 1 | 0 | 0 | 0 | | 0 | | 0 | s/o 33rd St - interplant vines w/in exisiting vine bed; turf restoration (Stat: 3616+50) |
| TOTAL | 391 | 10 | 22 | 1.9212 | 2569 | 3393 | 0 | 88 | 172.908 | 8527 | 0.13 | 0.973 | 49 | | 390 | | 1585 | |

LOCATION: I-94 (DAN RYAN EXPWY) ALONG SB DAN RYAN FROM 31ST TO I-57 AT ILL 1 (HALSTED ST) TO MLK DRIVE SPREADSHEET REFERENCES PLAN SHEETS WHICH WILL BE GIVEN TO THE CONTRACTOR BY THE ENGINEER.

ILLINOIS DEPARTMENT OF TRANSPORTATION

LANDSCAPE REPAIR LOCATION AND LAYOUT PLAN