


## SIDE ELEVATION OF LEFT REAR COLUMN AND FOUNDATION, LOCATION 18



## <u>NOTES</u>

 It shall be the Contractor's responsibility to verify all dimensions and conditions existing in the field prior to construction and ordering materials.

GR@EF***	W. Higgins Rood: Sulta : Chicado, Minols 60631 1773: 392-0112	280
uneer	1773) 399-0112	

H:\Jobs20#\20#30#2-44\CAD\Site\ 8/1/20#3 3:57:#PM

lto 280 31	USER NAME :	DESTONED -	REVISED
		CHECKED -	REVISED
	PLOT SCALE =	DRAWN - 08/01/2013	REVISED
	PLOT DATE =	CHECKED -	REVISED
		<del></del>	<del></del>