| VERIFIED UTILITY INFORMATION | | | | | | | | | |
|------------------------------|------------------|------------|------------|---------------------------|-----------------|------------------------|------------|--|--|
| TEST HOLE # | SIZE & TYPE | NORTHING | EASTING | EXISTING TOP ELEVATION | EXISTING CUT | REFERENCE ELEVATION | COMMENTS | | |
| 1 | N/A TUNNEL | 1897611.31 | 1171790.60 | 573.30′ | 7.17′ | 580.47′ | NORTH EDGE | | |
| 2 | N/A TUNNEL | 1897605.50 | 1171792.00 | 573.36′ | 6.92′ | 580.28′ | SOUTH EDGE | | |
| 3 | N/A TUNNEL | 1897600.91 | 1171359.65 | 573.15′ | 3.86′ | 577.01′ | NORTH EDGE | | |
| 4 | N/A TUNNEL | 1897595.46 | 1171360.49 | 573.09′ | 3.90′ | 576.99′ | SOUTH EDGE | | |
| 5 | N/A THRUST BLOCK | 1897513.66 | 1171678.90 | 589.72′ | 6.56′ | 596.28′ | | | |
| 5A | N/A THRUST BLOCK | 1897513.63 | 1171676.05 | 589.64′ | 7.20′ | 596.84′ | | | |
| 6 | N/A THRUST BLOCK | 1897522.75 | 1171594.74 | 589.37′ | 6.68′ | 596.05′ | | | |
| 6A | N/A THRUST BLOCK | 1897524.90 | 1171593.77 | 589.37′ | 6.76′ | 596.13′ | | | |
| 6B | N/A THRUST BLOCK | 1897525.17 | 1171595.71 | 589.38′ | 6.73′ | 596.11′ | | | |
| 7 | N/A THRUST BLOCK | 1897506.19 | 1171582.40 | 589.21′ | 6.36′ | 595.57′ | | | |
| 7 A | N/A THRUST BLOCK | 1897505.10 | 1171584.54 | 589.20′ | 6.42′ | 595.62′ | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | 1 | | | 1 | | | |

| NOTES | ABBREVIATIONS |
|--|---------------|
| NOTES TH #1 - Found North edge of what appears to be a 6' wide wooden frame around utility tunnel. Frame has appearance of wooden rail road ties. TH #2 - Found South edge of what appears to be a 6'' wide wooden frame around utility tunnel. Frame has appearance of wooden rail road ties. TH #3 - Found North edge of what appears to be a 6' wide wooden frame around utility tunnel. Frame has appearance of wooden rail road ties. Wooden frame is 5'' thick. TH #4 - Found South edge of what appears to be a 6' wide wooden frame around utility tunnel. Frame has appearance of wooden rail road ties. TH #5 - Found North edge of Thrust Block. | ABBREVIATIONS |
| TH #5A - Found North edge of Thrust Block. Reference point placed on east curb of driveway. TH #6 - Found West edge of Thrust Block. | |

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



Checked By: _ Date: ____

| DESIGNED | EG | REVISED | |
|----------|---------|---------|--|
| DRAWN | KC | REVISED | |
| CHECKED | KFS | REVISED | |
| DATE | 8/13/13 | REVISED | |

TH #6B - Found North edge of Thrust Block. TH #7 - Found North edge of Thrust Block.

TH #7A - Found North edge of Thrust Block.

TH #6A - Found a 90 degree bend on Thrust Block. Reference point placed in line with bend.

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** I-94/I-90/I-290 (Circle Interchange) Chicago, Illinois SHEET NO. TO STA. TBE Job No. IL09510531

COUNTY TOTAL SHEET NO. Cook 559 160 Contract No. N/A Job No.: P-91-259-12