Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 1 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Cra				Injury Sever	ity				
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
WEATHER CONDITION											
Clear	8	0	1	7	16	0	1	0	0	1	16
Cloudy/Overcast	1	0	0	1	2	0	0	0	0	0	2
Rain	1	0	0	1	2	0	0	0	0	0	2
Snow	1	0	1	0	4	0	3	0	1	2	2
TOTALS	11	0	2	9	24	0	4	0	1	3	22
TYPE OF CRASH											
Angle	2	0	0	2	4	0	0	0	0	0	6
Fixed Object	1	0	0	1	1	0	0	0	0	0	1
Overturned	1	0	0	1	1	0	0	0	0	0	1
Parked Motor Vehicle	1	0	0	1	2	0	0	0	0	0	1
Rear End	3	0	1	2	10	0	3	0	1	2	8
Sideswipe Opposite Direction	1	0	0	1	2	0	0	0	0	0	2
Sideswipe Same Direction	1	0	0	1	2	0	0	0	0	0	2
Turning	1	0	1	0	2	0	1	0	0	1	1
TOTALS	11	0	2	9	24	0	4	0	1	3	22

## Illinois Department of Transportation Division of Traffic Safety

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 2 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Cra	ashes						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
CLASS OF CITY											
0 TO 2,500	11	0	2	9	24	0	4	0	1	3	22
TOTALS	11	0	2	9	24	0	4	0	1	3	22
ROAD SURFACE CONDITION											
Dry	7	0	1	6	15	0	1	0	0	1	15
Ice	1	0	1	0	4	0	3	0	1	2	2
Snow or Slush	1	0	0	1	1	0	0	0	0	0	1
Wet	2	0	0	2	4	0	0	0	0	0	4
TOTALS	11	0	2	9	24	0	4	0	1	3	22

## Illinois Department of Transportation Division of Traffic Safety

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 3 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Num	nber of Crashes	6						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage		Total Vehicles	Total Total Killed Injured		А	В	С	0
CLASS OF TRAFFICWAY												
County & Local Roads Rural		6	0	0	6	11	0	0	0	0	0	10
Unmarked Highway Rural		5	0	2	3	13	0	4	0	1	3	12
TOTALS		11	0	2	9	24	0	4	0	1	3	22
DAY OF WEEK												
Monday		4	0	2	2	9	0	4	0	1	3	6
Tuesday		2	0	0	2	5	0	0	0	0	0	5
Wednesday		2	0	0	2	5	0	0	0	0	0	5
Thursday		1	0	0	1	1	0	0	0	0	0	1
Saturday		2	0	0	2	4	0	0	0	0	0	5
TOTALS		11	0	2	9	24	0	4	0	1	3	22

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 4 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Cra	ashes						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
TIME OF DAY											
06 AM	1	0	0	1	2	0	0	0	0	0	2
07 AM	1	0	1	0	2	0	1	0	0	1	1
08 AM	2	0	0	2	4	0	0	0	0	0	4
10 AM	1	0	0	1	3	0	0	0	0	0	3
1 PM	1	0	0	1	1	0	0	0	0	0	1
2 PM	1	0	1	0	4	0	3	0	1	2	2
5 PM	1	0	0	1	2	0	0	0	0	0	4
6 PM	1	0	0	1	3	0	0	0	0	0	3
10 PM	1	0	0	1	2	0	0	0	0	0	1
11 PM	1	0	0	1	1	0	0	0	0	0	1
TOTALS	11	0	2	9	24	0	4	0	1	3	22

# Illinois Department of Transportation

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 5 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Cra	ashes						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
LIGHT CONDITION											
Darkness	1	0	0	1	1	0	0	0	0	0	1
Darkness, Lighted Road	2	0	0	2	5	0	0	0	0	0	4
Daylight	7	0	2	5	16	0	4	0	1	3	13
Dusk	1	0	0	1	2	0	0	0	0	0	4
TOTALS	11	0	2	9	24	0	4	0	1	3	22
ROAD DEFECTS											
No Defects	11	0	2	9	24	0	4	0	1	3	22
TOTALS	11	0	2	9	24	0	4	0	1	3	22

## Illinois Department of Transportation Division of Traffic Safety

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 6 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Cr	ashes						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	A	В	С	0
TRAFFIC CONTROL											
No Controls	9	0	2	7	20	0	4	0	1	3	19
Stop Sign/Flasher	2	0	0	2	4	0	0	0	0	0	3
TOTALS	11	0	2	9	24	0	4	0	1	3	22
ROADWAY FEATURE											
Not Applicable	11	0	2	9	24	0	4	0	1	3	22
TOTALS	11	0	2	9	24	0	4	0	1	3	22

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 7 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

		Number Of Pe	rsons						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
DRIVER CONDITION											
Fatigued	1	0	1	0	1	0	0	0	0	0	1
Normal	20	0	5	15	20	0	4	0	1	3	16
Other/Unknown	2	0	0	2	2	0	0	0	0	0	2
TOTALS	23	0	6	17	23	0	4	0	1	3	19

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 8 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

			Number Of Pe	ersons						Injury Sever	ity	
Malta		Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
DRIVER AG	E/GENDER											
17												
	Female	1	0	0	1	1	0	0	0	0	0	1
18												
	Male	2	0	0	2	2	0	0	0	0	0	2
19												
	Female	1	0	1	0	1	0	1	0	1	0	0
20												
	Female	1	0	0	1	1	0	0	0	0	0	1
22-24												
	Female	2	0	1	1	2	0	1	0	0	1	1
	Male	1	0	0	1	1	0	0	0	0	0	1
25-29												
	Female	1	0	0	1	1	0	0	0	0	0	1
	Male	1	0	1	0	1	0	0	0	0	0	1
30-34												
	Female	1	0	0	1	1	0	0	0	0	0	1
	Male	1	0	0	1	1	0	0	0	0	0	1
35-39												
	Male	2	0	1	1	2	0	0	0	0	0	2
40-44												
	Male	3	0	1	2	3	0	1	0	0	1	2
45-49												
	Male	2	0	0	2	2	0	0	0	0	0	2
55-59												
	Male	1	0	1	0	1	0	1	0	0	1	0
60-64												
	Male	1	0	0	1	1	0	0	0	0	0	1
65-69												
	Male	1	0	0	1	1	0	0	0	0	0	1

## Illinois Department of Transportation Division of Traffic Safety

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 9 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

			Number Of Pe	ersons						Injury Sever	ity	
Malta		Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
DRIVER AGE/G	SENDER							·				
Unknown												
	Not Stated	1	0	0	1	1	0	0	0	0	0	1
TOTALS		23	0	6	17	23	0	4	0	1	3	19

Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 10 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

			Number Of Pe	ersons						Injury Sever	ity	
Malta		Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
PASSENGE	ER AGE/GENDER											
25-29												
	Male	1	0	1	0	1	0	0	0	0	0	1
60-64												
	Female	1	0	0	1	1	0	0	0	0	0	1
85-89												
	Male	1	0	0	1	1	0	0	0	0	0	1
TOTALS		3	0	1	2	3	0	0	0	0	0	3



Report Produced : 10/22/2019 11:30 AM

By: CENTRAL\HILLENAM

Page : 11 of 12

#### City Summary Crash Report

#### 1/1/2018 to 12/31/2018

City : Malta | \*See Notes at End of Report.

	Number Of Pe	ersons						Injury Sever	ity	
Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0

PEDALCYCLIST AGE/GENDER

		Number Of Ve	hicles						Injury Sever	ity	
Malta	Total	Fatal	Injury	Property Damage	Total Vehicles	Total Killed	Total Injured	А	В	С	0
VEHICLE DEFECTS											
None	22	0	6	16	22	0	4	0	1	3	20
Tires	1	0	0	1	1	0	0	0	0	0	1
Unknown	1	0	0	1	1	0	0	0	0	0	1
TOTALS	24	0	6	18	24	0	4	0	1	3	22
VEHICLE TYPE											
Passenger	10	0	3	7	10	0	2	0	1	1	8
Pickup	4	0	1	3	4	0	1	0	0	1	2
SUV	6	0	2	4	6	0	1	0	0	1	6
Tractor With Semi-Trailer	1	0	0	1	1	0	0	0	0	0	1
Unknown	1	0	0	1	1	0	0	0	0	0	1
Van/Mini-Van	2	0	0	2	2	0	0	0	0	0	4
TOTALS	24	0	6	18	24	0	4	0	1	3	22

#### <u>Notes</u>

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.

Report No : SDM-ERC117

Sorted by : City



Report Produced : 10/22/2019 11:30 AM By: CENTRAL\HILLENAM Page : 12 of 12

#### City Summary Crash Report

1/1/2018 to 12/31/2018