


→ GIZ

CONTROL POINT *1-



CONTROL AND TIES						
POINT #	NORTHING	EASTING	ELEVATION	DESCRIPTION		
CP #1	10000.000	10000.000	729.75	5%" I.P.		
CP #2	10149.610	10000.000	729.84	%" I.P.		

P	ROPOSED ALIGN	MENT
STATION	NORTHING	EASTING
10+00.00	9823.007	9951.698
15+10.00	10323.602	10049.195

BENCHMARK #1 = BENCHMARK DISC LOCATED IN CONCRETE HEADWALL OF CONCRETE ARCH VIADUCT STRUCTURE OVER SOUTH FORK OF KENT CREEK. THIS STRUCTURE IS LOCATED IMMEDIATELY NORTH OF CUNNINGHAM ROAD AND ABOUT 65 YARDS WEST OF SOUTH HORACE AVENUE. THE BENCHMARK DISK IS LOCATED IN SOUTH HEADWALL OF THE STRUCTURE ABOUT 2 FEET WEST OF EAST END OF HEADWALL, 1.5 FEET NORTH OF SOUTH EDGE OF HEADWALL, AND ABOUT 2 FEET BELOW LEVEL OF FORMER RAILROAD TRACK. ELEV. = 751.26

BENCHMARK *2 = SET SPIKE IN TREE LOCATED ON THE ROADWAY SIDE OF EXISTING FENCE PARALLEL TO HORACE AVENUE NEAR SOUTHEAST CORNER OF EXISTING STRUCTURE. TREE IS LOCATED ABOUT 65 FEET SOUTH AND ABOUT 30 FEET EAST OF THE CENTERLINE OF HORACE AVENUE. ELEV. = 729.62

NOTE:

THE TWO BENCHMARKS DESCRIBED IN PLANS WILL BE DESTROYED DURING CONSTRUCTION. CONTRACTOR WILL NEED TO ESTABLISH NEW BENCHMARKS.

REVISIO	ONS		
REVISION NAME		DATE	
	-		
	-		
	1 1	i	Ĕ

ILLINOIS DEPARTMENT OF TRANSPORTATION
F.A.U. 5100
SECTION 04-00526-00-BR
CITY OF ROCKFORD. IL
HORACE AVE. OVER S. FORK KENT CREEK

ALIGNMENT AND TIES

SCALE: VERT. -HORIZ. -DATE 03/22/05

DRAWN BY RLA CHECKED BY JDS

LAYOUT RLA 02/23/05 rto
DRAWN RLA 02/25/05 03/17/2005

Hanson Professional Services Inc.